


## Quick Guide

---

### Steps to Update Virtual COM Driver

1. Connect the handheld scanner and the host (e.g. a PC) with a USB interface cable.
2. Enable USB virtual COM port with programming barcodes.


Enter/Exit Programming Mode



Enable USB virtual COM



Enter/Exit Programming Mode



3. After the programming, the host would request driver installation. Browse your files to locate the driver and start installation. For Windows based systems:

- Open Device Manager and select the barcode scanner you want to update
- Select install driver from a specific location.
- Direct the folder for .inf file.
- Ignore the warning and continue with installation
- A COM port is assigned to the scanner when installation is complete